## Amazonas Mid-Air (Sep. 29, 2006)

Analyst: Jörn Stuphorn

Report created on: Mon Sep 17 19:47:23 CEST 2007

Document version: Document version unknown



**Causalis Limited** 

Am Petersberg 3 D-33619 Bielefeld

mail: info@causalis.com web: http://www.causalis.com tel: +49 521 3 29 31 00 fax: +49 521 3 29 31 02

# INCIDENT ANALYSIS

#### Incident description:

Information taken from IHT Sep 30, 2006 to May 03, 2007, NYT Sep 30, 2006 to May 03, 2007, Flight International Oct 10-16, 2006 to May 08-14, 2007, Aviation Week Oct 9, 2006 to Apr. 30, 2007, NTSB Safety Recommendation May 2, 2007 and the NTSB Factual Report.

## Legend of Factorshapes



**Event** 

**Un-Event** 

State


Process

Assumption

Countermeasure

Contraindication

## Why-Because Graph



## Timeline of Events

							Tower
		GOL Flight 1907	Embraer Legacy	Radar operator ATC Brasilia	ATC Manaus	TCAS System	Sao Jose dos Campos Tower
Legacy takes off from Sao Jose dos Campos with destination Manaus.	14:51:00	)	X				Χ
Legacy cleared by Tower Jose dos Campos for FL370	15:11:00					X	X
Legacy flies at FL370	15:33:00	)	Χ				
Flight 1907 from Manaus to Brasilia	15:35:00	Χ					
ATC Brasilia makes blind transmission ordering Legacy Crew to switch radio frequencies	15:51:00	)	Χ	X			
Lecagy passes waypoint Brasilia	15:56:00	2	X				
Boeing B737 flies at FL370	15:58:00	Χ					
Legacy Transponder not broadcasting	16:02:00	2	X				
ATC Brasilia looses secondary radar information on Legacy		)	Χ	X			
ATC Brasilia transmits blindly to Legacy	16:26:00	)	Χ	X			
ATC Brasilia has lost primary radar contact with Legacy	16:30:00	)	Χ	X			
Legacy tracked intermittendly by primary radar	16:38:00	)	Χ	X			
Legacy crew misheard frequency	16:53:00	)	Χ	X			
Legacy collides with Boeing B737	16:57:00	X	Χ				
Legacy transponder resumes broadcasting	17:02:00	)	<b>X</b> >	<			

## Factor List

- 1 Boeing B737 wreckage found
- 2 Boeing B737 crashes in Mato Grosso area
- 3 Boeing B737-800 operated by GOL
- 4 Possible Mid-Air with smaller plane
- 5 Radar contact lost during flight
- 6 Flight 1907 from Manaus to Brasilia
- 7 Legacy collides with "shadow"
- 8 Legacy looses part of a wing
- 9 Radar shows altitude difference of about 1000 feet
- 10 Boeing B737 carrying 149 passengers, 6 crew
- 11 GOL 1907 had 200 flight hours
- 12 Legacy makes emergency landing at Cachimbo air force base
- 13 Boeing B737 strikes ground at more than 300 mph
- 14 Unlikelyhood of survivors
- 15 Some kind of contact between Boeing 737 and Legacy
- 16 Legacy on inaugural flight to United States
- 17 Legacy purchased by ExcelAire
- 18 Legacy takes off from Sao Jose dos Campos with destination Manaus.
- 19 Legacy briefly looses flight stability, but recovers
- 20 Legacy tail damaged
- 21 Legacy does not see Boeing B737
- 22 Lecagy flies stable northwest at FL370
- 23 Legacy equipped with anticollision device
- 24 Boeing B737 equipped with anticollision device
- 25 Legacy might have flown off course
- 26 Boeing B737 might have had trouble
- 27 Boeing B737 might have lost parts
- 28 Parts of B737 might have hit Legacy
- 29 Possible lack of coordination among air traffic controllers
- 30 149 passengers and 6 crew die
- 31 Possible negligence or disregard for air-traffic instructions
- 32 Failure to detect other aircraft
- 33 Air-traffic controllers not alerted of dangerous flight path
- 34 Crew ignored instruction to descent from FL370 to FL360 passing Brasilia
- 35 Crew decided to fly higher without alerting controllers
- 36 Boeing B737 flies at FL370
- 37 Boeing B737 visible on radar until accident
- 39 Technical warning system does not operate as expected
- 40 Crew unable to find proper frequency for Manaus controllers
- 41 No radio contact between Legacy and Brasilia or Manaus until collision
- 42 TCAS on board Legacy is turned off or not working
- 43 Handover from Brasilia to Manaus required
- 44 148 passengers and 6 crew die
- 45 Controller unable to gauge altitude by radar
- 46 Single electronic failure on board of the Legacy
- 47 ATC Brasilia makes blind transmission ordering Legacy Crew to switch radio frequencies
- 48 Legacy enters jurisdiction of different ATC Center
- 49 Legacy crew misheard frequency
- 50 Crew unable to tune radio correctly
- 51 Legacy transponder resumes broadcasting
- 52 Legacy tracked intermittendly by primary radar
- 53 Primary radar gives no altitude information
- 54 Controller does not warn about possible collision

- 55 Software requires altitude information for collision warning
- 56 Legacy Transponder not broadcasting
- 57 TCAS requires Transponder information for operation
- 58 Boeing B737 not advised to change altitude
- 59 Complete radar and radio coverage over jungle
- 60 Discrepancy between Legacy flightpath, altitude and altitude assignment
- 61 Legacy does not take evasive action
- 62 Assumed Mid-Air Collision
- 63 Both aircraft at FL370
- 64 Legacy flies at FL370
- 65 Both aircraft on same airway
- 66 Legacy TCAS manufactured by Honeywell
- 67 FAA had ordered recall on TCAS model used in Legacy
- 68 TCAS device tended to stop broadcasting unexpectedly in certain circumstances
- 69 Legacy Flightplan called for FL380 at point of collision
- 70 Boeing B737 CVR lost in rainforest
- 71 Brazilian Air Traffic System run by Brazilian Air Force
- 72 Takeoff Clearance called for FL370 for the entire route
- 73 ATC instruction supersedes flight plan
- 74 Boeing B737 CVR found
- 75 Legacy cleared by Tower Jose dos Campos for FL370
- 76 Legacy collides with Boeing B737
- 77 19 unsuccessful attempts to reach ATC Brasilia
- 78 Boeing B737 flight plan called for FL410 at point of collision
- 79 ATC Manaus instructed Boeing B737 to fly at FL370
- 80 ATC believed the Legacy to fly at FL360
- 81 Possible Cause for (56)
- 82 Avionics component has operational problems
- 83 Avionics component returned to Honeywell
- 84 Honeywell returned avionics component to Embraer
- 85 Embraer installed avionics component
- 86 One transponder and some radio communications systems installed in avionics component
- 87 Cockpit systems do not effectively alert Legacy crew of anti-collision equipment failure
- 88 Boeing unable to avoid collision
- 89 Boeing crew has no visual identification of conflicting traffic
- 90 Legacy not advised to change altitude
- 91 Boeing B737 spirals out of control
- 92 Boeing B737 breaks up in mid-air
- 93 Both aircraft on airway UZ6 in opposite directions
- 96 Radar coverage limits at boarder between airspace sectors
- 97 Notoriously unreliable radio communications in area of collision
- 98 Boeing B737 in contact with Manaus
- 99 Legacy technically under control of ATC Brasilia
- 100 Controller Brasilia does not warn Legacy
- 101 Controller Manaus did not warn Boeing B737
- 102 No handover of Legacy from Brasilia to Manaus
- 103 Unknown cause
- 104 Legacy winglet severed Boeing B737 hydraulic and electrical lines
- 105 Legacy winglet compromised Boeing B737 left wing's aileron actuators
- 106 Legacy winglet deforms Boeing B737 wing
- 107 Procedure to maintain current flight level "for a short time"
- 108 Legacy does not change altitude
- 109 Boeing B737 does not take evasive action
- 110 ATC Brasilia looses secondary radar information on Legacy
- 111 ATC Brasilia has lost primary radar contact with Legacy

- 112 ATC Brasilia transmits blindly to Legacy
- 113 Secondary radar information trasmits altitude information
- 115 ATC monitoring system automatically updates altitude information on controller's display
- 116 Lecagy passes waypoint Brasilia
- 117 System "feature": Displayed altitude set to altitude given in flight plan after passing of waypoint
- 118 Brazilian military 3-d primary radar provides flight altitude information
- 119 Military Primary radar altitude information presented to civilian controllers
- 120 Military 3-D primary radar altitude information inacurrate
- 121 Long-Range triangulation
- 122 Controller does not trust primary radar altitude information
- 123 Legacy enters UZ6
- 124 UZ6 connects Manaus and Brasilia
- 125 Boeing B737 uses UZ6
- 126 Legacy flightplan
- 127 Planned altitude change from FL370 to FL360 after passing waypoint Brasilia
- 128 Planned altitude change from FL360 to FL380 after passing TERES
- 129 Legacy crew identifies TCAS failure
- 130 TCAS unit displays "TCAS OFF in small white letters on flight display
- 131 ATC shift change
- 132 Controller's electronic flight strip showed Legacy as assigned to FL360
- 133 Boeing B737 flightplan requested FL370 as cruise altitude
- 134 No aural warning on TCAS failure
- 135 Boeing B737 does not change altitude
- 136 Legacy maintains FL370
- 137 Placing of Legacy crew feet might have disabled Legacy communication devices

## Factor List - Details

1 Boeing B737 wreckage found

Type of Factor: Event

Date/Time:

Actors involved: Boeing B737-800

Annotation: Reuters report, IHT Sep 30, 2006

2 Boeing B737 crashes in Mato Grosso area

Type of Factor: Event

Date/Time:

Actors involved: Boeing B737-800 Annotation: evidenced by Factor 1

Boeing B737-800 operated by GOL

Type of Factor: State

Date/Time:

3

Actors involved: Boeing B737-800

Annotation: Reuters report, IHT Sep 30, 2006

4 Possible Mid-Air with smaller plane

Type of Factor: Assumption

Date/Time:

Actors involved: Boeing B737-800

**Embraer Legacy** 

Annotation: Reuters report, IHT Sep 30, 2006

quoting local officials and media reports

5 Radar contact lost during flight

Type of Factor: State

Date/Time:

Actors involved: Boeing B737-800

Radar operator

Annotation: Reuters report, IHT Sep 30, 2006

6 Flight 1907 from Manaus to Brasilia

Type of Factor: Process

Date/Time: 29.09.2006 15:35:00 Actors involved: Boeing B737-800

Annotation: Reuters report, IHT Sep 30, 2006

7 Legacy collides with "shadow"

Type of Factor: Event

Date/Time:

Actors involved: Embraer Legacy

Annotation: Statement of Defense Minister Waldir Pires on Band TV

8 Legacy looses part of a wing

Type of Factor: Event

Date/Time:

Actors involved: Embraer Legacy

Annotation: Statement of Defense Minister Waldir Pires on Band TV

9 Radar shows altitude difference of about 1000 feet

Type of Factor: State

Date/Time:

Actors involved: Boeing B737-800

**Embraer Legacy** 

AirTrafficControl Brasila (CINDACTA 1)

AirTrafficControl Manaus

Annotation: Reuters report, IHT Sep 30, 2006

#### 10 Boeing B737 carrying 149 passengers, 6 crew

Type of Factor: Unspecified

Date/Time:

Actors involved: Boeing B737-800

Annotation: Reuters report, IHT Sep 30, 2006

Statement by GOL

#### 11 GOL 1907 had 200 flight hours

Type of Factor: Unspecified

Date/Time:

Actors involved: Boeing B737-800

Annotation: Reuters report, IHT Sep 30, 2006

#### 12 Legacy makes emergency landing at Cachimbo air force base

Type of Factor: Event

Date/Time:

Actors involved: Embraer Legacy

Annotation: Reuters report, IHT Sep 30 2006

Statement of Defense Minister Waldr Pires on Band TV

#### 13 Boeing B737 strikes ground at more than 300 mph

Type of Factor: Event

Date/Time:

Actors involved: Boeing B737-800

Annotation: AP report, IHT Oct 1, 2006

quoting Jose Carlos Pereira, president of Brazil's airport authority

#### 14 Unlikelyhood of survivors

Type of Factor: Assumption

Date/Time:

Actors involved: Boeing B737-800

Annotation: AP report, IHT Oct 1, 2006

quoting Jose Carlos Pereira, president of Brazil's airport authority

#### 15 Some kind of contact between Boeing 737 and Legacy

Type of Factor: Unspecified

Date/Time:

Actors involved: Boeing B737-800

**Embraer Legacy** 

Annotation: AP report, IHT Oct 1, 2006

quoting Jose Carlos Pereira, president of Brazil's airport authority

#### 16 Legacy on inaugural flight to United States

Type of Factor: Unspecified

Date/Time:

Actors involved: Embraer Legacy

Annotation: AP report, IHT Oct 1, 2006

#### 17 Legacy purchased by ExcelAire

Type of Factor: Event

Date/Time:

Actors involved: Embraer Legacy

Annotation: AP report, IHT Oct 1, 2006

quoting Embraer and Milton Zuanazzi, general director for Brazil's Civil Aviation Agency

Authority

## 18 Legacy takes off from Sao Jose dos Campos with destination Manaus.

Type of Factor: Process

Date/Time: 29.09.2006 14:51:00 Actors involved: Embraer Legacy

Air Traffic Control at Sao Jose dos Campos Airport, Brazil

Annotation: AP report, IHT Oct 1, 2006

quoting Diane McNulty, New York Times sopkeswoman

#### 19 Legacy briefly looses flight stability, but recovers

Type of Factor: Process

Date/Time:

Actors involved: Embraer Legacy

Annotation: AP report, IHT Oct 1, 2006

quoting Joe Sharkey, passenger on Legacy after Diane McNulty

#### 20 Legacy tail damaged

Type of Factor: Event

Date/Time:

Actors involved: Embraer Legacy
Annotation: New York Times
Oct 01, 2006

#### 21 Legacy does not see Boeing B737

Type of Factor: UnEvent

Date/Time:

Actors involved: Embraer Legacy

Boeing B737-800

Annotation: New York Times

Oct 01, 2006

quoting Joe Sharkey

#### 22 Lecagy flies stable northwest at FL370

Type of Factor: Assumption

Date/Time:

Actors involved: Embraer Legacy
Annotation: New York Times

Oct 01, 2006

quoting Joe Sharkey

#### 23 Legacy equipped with anticollision device

Type of Factor: State

Date/Time:

Actors involved: Embraer Legacy

Collision Avoidance System

Annotation: New York Times

Oct 01, 2006

quoting "authorities"

#### 24 Boeing B737 equipped with anticollision device

Type of Factor: State

Date/Time:

Actors involved: Boeing B737-800

Collision Avoidance System

Annotation: New York Times

Oct 01, 2006

quoting "authorities"

## 25 Legacy might have flown off course

Type of Factor: Assumption

Date/Time:

Actors involved: Embraer Legacy Annotation: New York Times

Oct 02, 2006

quoting unidentified sources in the Brazilian Air Force

#### 26 Boeing B737 might have had trouble

Type of Factor: Assumption

Date/Time: Actors involved:

Annotation: **New York Times** 

Oct 02, 2006

quoting "Others"

#### 27 Boeing B737 might have lost parts

Type of Factor: Assumption

Date/Time: Actors involved:

Annotation: **New York Times** 

Oct 02, 2006

quoting "Others"

#### 28 Parts of B737 might have hit Legacy

Type of Factor: Assumption

Date/Time:

Actors involved: Boeing B737-800

**Embraer Legacy** 

Annotation: **New York Times** 

Oct 02, 2006

quoting "Others"

#### 29 Possible lack of coordination among air traffic controllers

Type of Factor: Assumption

Date/Time:

Actors involved: Radar operator

Annotation: IHT

Oct 03, 2006

quoting Brazilian news reports

#### 149 passengers and 6 crew die 30

Type of Factor: Event

Date/Time:

Actors involved: Boeing B737-800 Annotation: **New York Times** Oct 04, 2006

revised to 148 pax, 6 crew by Factor 44

#### 31 Possible negligence or disregard for air-traffic instructions

Type of Factor: Assumption

Date/Time: Actors involved:

Annotation: **New York Times** 

Oct 04, 2006

#### 32 Failure to detect other aircraft

Type of Factor: Assumption

Date/Time:

Actors involved: Boeing B737-800

**Embraer Legacy** 

Annotation: **New York Times** 

Oct 04, 2006

#### 33 Air-traffic controllers not alerted of dangerous flight path

Type of Factor: Assumption

Date/Time:

Actors involved: Radar operator Annotation: **New York Times** 

Oct 04, 2006

## 34 Crew ignored instruction to descent from FL370 to FL360 passing Brasilia

Type of Factor: Assumption

Date/Time:

Actors involved: Embraer Legacy
Annotation: New York Times
Oct 04, 2006

quoting prosecutor Mr. Alves

#### 35 Crew decided to fly higher without alerting controllers

Type of Factor: Assumption

Date/Time:

Actors involved: Embraer Legacy
Annotation: New York Times
Oct 04, 2006

quoting prosecutor Mr. Alves

#### 36 Boeing B737 flies at FL370

Type of Factor: Process

Date/Time: 29.09.2006 15:58:00
Actors involved: Boeing B737-800
Annotation: New York Times
Oct 02, 2006

### 37 Boeing B737 visible on radar until accident

Type of Factor: State

Date/Time:

Actors involved: Boeing B737-800

AirTrafficControl Manaus

Annotation: New York Times

Oct 05, 2006

quoting Braizilian Air Force investigators

#### 39 Technical warning system does not operate as expected

Type of Factor: UnEvent

Date/Time:

Actors involved: Embraer Legacy

Collision Avoidance System

Annotation: New York Times

Oct 05, 2006

quoting Testimony of Legacy pilots

#### 40 Crew unable to find proper frequency for Manaus controllers

Type of Factor: UnEvent

Date/Time:

Actors involved: Embraer Legacy
Annotation: New York Times
Oct 05, 2006

Oct 03, 2000

quoting Testimony of Legacy pilots

## 41 No radio contact between Legacy and Brasilia or Manaus until collision

Type of Factor: State

Date/Time:

Actors involved: Embraer Legacy

AirTrafficControl Brasila (CINDACTA 1)

AirTrafficControl Manaus

Annotation: New York Times

Oct 05, 2006

quoting Testimony of Legacy pilots

#### 42 TCAS on board Legacy is turned off or not working

Type of Factor: Assumption

Date/Time:

Actors involved: Embraer Legacy

Collision Avoidance System

Annotation: New York Times

Oct 05, 2006

quoting procecutor Adriano Alves

### 43 Handover from Brasilia to Manaus required

Type of Factor: Process

Date/Time:

Actors involved: Embraer Legacy

AirTrafficControl Brasila (CINDACTA 1)

AirTrafficControl Manaus

Annotation: New York Times

Oct 05, 2006

quoting Testimony of Legacy pilots

#### 44 148 passengers and 6 crew die

Type of Factor: Event

Date/Time:

Actors involved: Boeing B737-800
Annotation: New York Times

Oct 06, 2006

revised passenger count by GOL

#### 45 Controller unable to gauge altitude by radar

Type of Factor: UnEvent

Date/Time:

Actors involved: Embraer Legacy

AirTrafficControl Brasila (CINDACTA 1)

Annotation: New York Times

Oct 06, 2006

quoting Brazilian officials

#### 46 Single electronic failure on board of the Legacy

Type of Factor: Assumption

Date/Time:

Actors involved: Embraer Legacy
Annotation: New York Times
Oct 06, 2006

quoting Technial Experts

#### 47 ATC Brasilia makes blind transmission ordering Legacy Crew to switch radio frequencies

Type of Factor: Event

Date/Time: 29.09.2006 15:51:00 Actors involved: Embraer Legacy

AirTrafficControl Brasila (CINDACTA 1)

Annotation: New York Times

Oct 06, 2006

quoting police official

## 48 Legacy enters jurisdiction of different ATC Center

Type of Factor: Event

Date/Time:

Actors involved: Embraer Legacy

AirTrafficControl Brasila (CINDACTA 1)

AirTrafficControl Manaus

Annotation: New York Times

Oct 06, 2006

quoting police official

#### 49 Legacy crew misheard frequency

Type of Factor: Event

Date/Time: 29.09.2006 16:53:00 Actors involved: Embraer Legacy

AirTrafficControl Brasila (CINDACTA 1)

Annotation: New York Times

Oct 06, 2006

quoting police official

#### 50 Crew unable to tune radio correctly

Type of Factor: Event

Date/Time:

Annotation:

Actors involved: Embraer Legacy Annotation: New York Times

Oct 06, 2006

quoting police official

#### 51 Legacy transponder resumes broadcasting

Type of Factor: Event

Date/Time: 29.09.2006 17:02:00 Actors involved: Embraer Legacy

Radar operator New York Times

Oct 06, 2006

quoting Brazilian officials

#### 52 Legacy tracked intermittently by primary radar

Type of Factor: Process

Date/Time: 29.09.2006 16:38:00 Actors involved: Embraer Legacy

AirTrafficControl Brasila (CINDACTA 1)

Annotation: New York Times

Oct 06, 2006

quoting General Pinheiro

refined by Flight International Nov. 21-27, 2006

#### 53 Primary radar gives no altitude information

Type of Factor: Un-Event

Date/Time:

Actors involved: Radar operator
Annotation: New York Times
Oct 06, 2006

#### 54 Controller does not warn about possible collision

Type of Factor: Un-Event

Date/Time:

Actors involved: Radar operator
Annotation: New York Times
Oct 06, 2006

quoting General Pinheiro

#### 55 Software requires altitude information for collision warning

Type of Factor: State

Date/Time:

Actors involved: Radar operator Annotation: **New York Times** Oct 06, 2006

deduced from 54

#### Legacy Transponder not broadcasting 56

Type of Factor: UnEvent

29.09.2006 16:02:00 Date/Time: Actors involved: Embraer Legacy **New York Times** Annotation: Oct 06, 2006

quoting General Pinheiro

#### 57 TCAS requires Transponder information for operation

Type of Factor: State

Date/Time:

Actors involved: Collision Avoidance System

**Embraer Legacy** 

**New York Times** Annotation:

Oct 06, 2006

#### 58 Boeing B737 not advised to change altitude

Type of Factor: UnEvent

Date/Time:

Actors involved: Boeing B737-800

AirTrafficControl Manaus

Annotation: **New York Times** 

Oct 06, 2006

derived from available information and statement from John Cox

#### 59 Complete radar and radio coverage over jungle

Type of Factor: State

Date/Time:

Actors involved: Radar operator **New York Times** Annotation: Oct 06, 2006

quoting General Vilarinha

#### Discrepancy between Legacy flightpath, altitude and altitude assignment 60

Type of Factor: State

Date/Time: Actors involved:

**New York Times** Annotation:

Oct 06, 2006

#### 61 Legacy does not take evasive action

Type of Factor: UnEvent

Date/Time:

Actors involved: Embraer Legacy

Annotation: **Derived from Crew Testimony** 

#### 62 **Assumed Mid-Air Collision**

Type of Factor: Assumption

Date/Time:

Actors involved: Boeing B737-800

**Embraer Legacy** 

Annotation: superseded by Factor 76

#### 63 Both aircraft at FL370

Type of Factor: State

Date/Time:

Actors involved: Boeing B737-800

**Embraer Legacy** 

Annotation:

#### 64 Legacy flies at FL370

Type of Factor: Process

Date/Time: 29.09.2006 15:33:00 Actors involved: Embraer Legacy

Annotation: Testimony of Legacy Crew

#### 65 Both aircraft on same airway

Type of Factor: Process

Date/Time:

66

Actors involved: Boeing B737-800

**Embraer Legacy** 

Annotation: Derived from Flightplans Legacy TCAS manufactured by Honeywell

Type of Factor: State

Date/Time: Actors involved:

Annotation: New York Times

Oct 08, 2006

guting ExcelAire

#### 67 FAA had ordered recall on TCAS model used in Legacy

Type of Factor: Assumption

Date/Time: Actors involved:

Annotation: New York Times

Oct 08, 2006

quoting ExcelAire

False information, corrected by New York Times, Oct 09, 2006

## 68 TCAS device tended to stop broadcasting unexpectedly in certain circumstances

Type of Factor: Assumption

Date/Time:
Actors involved:

Annotation: New York Times

Oct 08, 2006

quoting ExcelAire

TCAS on board Legacy was not recalled by FAA, New York Times Oct 09, 2006

#### 69 Legacy Flightplan called for FL380 at point of collision

Type of Factor: State

Date/Time:

Actors involved: Embraer Legacy
Annotation: New York Times

Oct 12, 2006

quoting police officials

#### 70 Boeing B737 CVR lost in rainforest

Type of Factor: State

Date/Time:

Actors involved: Boeing B737-800
Annotation: New York Times
Oct 12, 2006

superseded by Factor 74

#### 71 Brazilian Air Traffic System run by Brazilian Air Force

Type of Factor: State

Date/Time: Actors involved:

Annotation: New York Times

Oct 12, 2006

#### 72 Takeoff Clearance called for FL370 for the entire route

Type of Factor: Event

Date/Time:

Actors involved: Radar operator

Embraer Legacy

Annotation: New York Times

Oct 28, 2006

quoting Crew lawyer Robert A. Torricella Jr.

supported by Factor 75

#### 73 ATC instruction supersedes flight plan

Type of Factor: State

Date/Time:

Actors involved: Embraer Legacy

Air Traffic Control at Sao Jose dos Campos Airport, Brazil

Annotation: New York Times

Oct 28, 2006

quoting Crew lawyer Roberto A. Torricella Jr.

generalised, following New York Times, Nov 21, 2006

#### 74 Boeing B737 CVR found

Type of Factor: Event

Date/Time: Actors involved:

Annotation: New York Times

Oct 28, 2006

#### 75 Legacy cleared by Tower Jose dos Campos for FL370

Type of Factor: Event

Date/Time: 29.09.2006 15:11:00

Actors involved: Pilot of Embrear Legacy 600XL

Air Traffic Control at Sao Jose dos Campos Airport, Brazil

Annotation: AP report, IHT

Nov 02, 2006

quoting Brazilian newspaper "Folha"

"Folha" allegedly gained access to CVR transcript

confirmed by Brazilian Air Force preliminary report

#### 76 Legacy collides with Boeing B737

Type of Factor: Event

Date/Time: 29.09.2006 16:57:00 Actors involved: Boeing B737-800

**Embraer Legacy** 

Annotation: New York Times

Nov 21, 2006

#### 77 19 unsuccessful attempts to reach ATC Brasilia

Type of Factor: Event

Date/Time:

Actors involved: Embraer Legacy
Annotation: New York Times
Nov 21, 2006

## Boeing B737 flight plan called for FL410 at point of collision

Type of Factor: State

Date/Time:

78

Actors involved: Boeing B737-800
Annotation: New York Times
Nov 21, 2006

#### 79 ATC Manaus instructed Boeing B737 to fly at FL370

Type of Factor: Event

Date/Time:

Actors involved: Boeing B737-800

AirTrafficControl Brasila (CINDACTA 1)

Annotation: New York Times Nov 21, 2006

#### 80 ATC believed the Legacy to fly at FL360

Type of Factor: State

Date/Time:

Annotation:

Actors involved: AirTrafficControl Brasila (CINDACTA 1)

AirTrafficControl Manaus

Embraer Legacy
AP report, IHT

Dec 05, 2006

quoting Brig. Gen. Luiz Carlos da Silva Bueno

#### 81 Possible Cause for (56)

Type of Factor: Assumption

Date/Time: Actors involved:

Annotation: structural node

#### 82 Avionics component has operational problems

Type of Factor: State

Date/Time:

Actors involved: Collision Avoidance System

Annotation: AP report, IHT Apr 21, 2007

quoting ExcelAire report to Brazilian federal police

#### 83 Avionics component returned to Honeywell

Type of Factor: Process

Date/Time:

Actors involved: Collision Avoidance System

Annotation: AP report, IHT

Apr 21, 2007

quoting ExcelAire report to Brazilian federal police

#### 84 Honeywell returned avionics component to Embraer

Type of Factor: Process

Date/Time:

Actors involved: Collision Avoidance System Annotation: Derived from 83 and 85

#### 85 Embraer installed avionics component

Type of Factor: Event

Date/Time:

Actors involved: Embraer Legacy
Annotation: AP report, IHT
Apr 21, 2007

quoting ExcelAire report to Brazilian federal police

#### 86 One transponder and some radio communications systems installed in avionics component

Type of Factor: State

Date/Time:

Actors involved: Collision Avoidance System

Annotation: AP report, IHT

Apr 21, 2007

quoting ExcelAire report to Brazilian federal police

#### 87 Cockpit systems do not effectively alert Legacy crew of anti-collision equipment failure

Type of Factor: UnEvent

Date/Time:

Actors involved: Collision Avoidance System

**Embraer Legacy** 

Annotation: IHT

May 03, 2007

quoting US air safety investigators

#### 88 Boeing unable to avoid collision

Type of Factor: Event

Date/Time:

Actors involved: Boeing B737-800

Annotation:

#### 89 Boeing crew has no visual identification of conflicting traffic

Type of Factor: Assumption

Date/Time:

Actors involved: Boeing B737-800

Annotation:

### 90 Legacy not advised to change altitude

Type of Factor: UnEvent

Date/Time:

Actors involved: Embraer Legacy

AirTrafficControl Brasila (CINDACTA 1)

Annotation:

#### 91 Boeing B737 spirals out of control

Type of Factor: Event

Date/Time:

Actors involved: Boeing B737-800

Annotation: Flight International Oct 10-16, 2006

## Boeing B737 breaks up in mid-air

Type of Factor: Event

Date/Time:

92

Actors involved: Boeing B737-800
Annotation: Flight International Oct 10-16, 2006

#### 93 Both aircraft on airway UZ6 in opposite directions

Type of Factor: Process

Date/Time:

Actors involved: Boeing B737-800

**Embraer Legacy** 

Annotation: Flight International

Oct 10-16, 2006

#### 96 Radar coverage limits at boarder between airspace sectors

Type of Factor: Unspecified

Date/Time: Actors involved:

Annotation: Flight International

Oct 10-16, 2006

### 97 Notoriously unreliable radio communications in area of collision

Type of Factor: State

Date/Time: Actors involved:

Annotation: Flight International

Oct 10-16, 2006

quoting local pilots

#### 98 Boeing B737 in contact with Manaus

Type of Factor: State

Date/Time:

Actors involved: Boeing B737-800

AirTrafficControl Manaus

Annotation: Flight International

Oct 10-16, 2006

#### 99 Legacy technically under control of ATC Brasilia

Type of Factor: State

Date/Time:

Actors involved: Embraer Legacy

AirTrafficControl Brasila (CINDACTA 1)

Annotation: Flight International

Oct 10-16, 2006

#### 100 Controller Brasilia does not warn Legacy

Type of Factor: UnEvent

Date/Time:

Actors involved: AirTrafficControl Brasila (CINDACTA 1)

**Embraer Legacy** 

Annotation: Splitted up Factor 54

### 101 Controller Manaus did not warn Boeing B737

Type of Factor: UnEvent

Date/Time:

Actors involved: AirTrafficControl Manaus

Boeing B737-800

Annotation: Splitted up Factor 54

#### 102 No handover of Legacy from Brasilia to Manaus

Type of Factor: Assumption

Date/Time:

Actors involved: Embraer Legacy

AirTrafficControl Brasila (CINDACTA 1)

AirTrafficControl Manaus

Annotation: Needed factor for Factor 101

#### 103 Unknown cause

Type of Factor: Assumption

Date/Time: Actors involved: Annotation:

#### 104 Legacy winglet severed Boeing B737 hydraulic and electrical lines

Type of Factor: Assumption

Date/Time:

Actors involved: Boeing B737-800

**Embraer Legacy** 

Annotation: Flight International

Oct. 17-23, 2006

#### 105 Legacy winglet compromised Boeing B737 left wing's aileron actuators

Type of Factor: Assumption

Date/Time:

Actors involved: Boeing B737-800

**Embraer Legacy** 

Annotation: Flight International

Oct. 17-23, 2006

#### 106 Legacy winglet deforms Boeing B737 wing

Type of Factor: Assumption

Date/Time:

Actors involved: Boeing B737-800

**Embraer Legacy** 

Annotation: Flight International

Oct. 17-23, 2006

#### 107 Procedure to maintain current flight level "for a short time"

Type of Factor: Process

Date/Time:

Actors involved: Embraer Legacy
Annotation: Flight International

Oct. 17-23, 2006

citing ICAO procedures for pilots under ATC control by radar, who are aware they have lost

communication

#### 108 Legacy does not change altitude

Type of Factor: Event

Date/Time:

Actors involved: Embraer Legacy

Annotation: Derived from 64, 90, 107 Boeing B737 does not take evasive action

Type of Factor: UnEvent

Date/Time:

109

Actors involved: Boeing B737-800
Annotation: Flight International

Oct 21-27, 2006

## 110 ATC Brasilia looses secondary radar information on Legacy

Type of Factor: State

Date/Time: 29.09.2006 16:02:00

Actors involved: AirTrafficControl Brasila (CINDACTA 1)

**Embraer Legacy** 

Annotation: Flight International

Oct 21-27, 2006

#### 111 ATC Brasilia has lost primary radar contact with Legacy

Type of Factor: State

Date/Time: 29.09.2006 16:30:00

Actors involved: AirTrafficControl Brasila (CINDACTA 1)

**Embraer Legacy** 

Annotation: Flight International

Oct 21-27, 2006

#### 112 ATC Brasilia transmits blindly to Legacy

Type of Factor: Process

Date/Time: 29.09.2006 16:26:00

Actors involved: AirTrafficControl Brasila (CINDACTA 1)

**Embraer Legacy** 

Annotation: Flight International

Oct 21-27, 2006

#### 113 Secondary radar information trasmits altitude information

Type of Factor: State

Date/Time: Actors involved: Annotation:

#### 115 ATC monitoring system automatically updates altitude information on controller's display

Type of Factor: Process

Date/Time:

Actors involved: AirTrafficControl Brasila (CINDACTA 1)

Annotation: Flight International Dec. 05-11, 2006

quoting IFATCA

### 116 Lecagy passes waypoint Brasilia

Type of Factor: Event

Date/Time: 29.09.2006 15:56:00
Actors involved: Embraer Legacy
Annotation: Flight International
Dec. 05-11, 2006

auotina IFATCA

#### 117 System "feature": Displayed altitude set to altitude given in flight plan after passing of waypoint

Type of Factor: State

Date/Time:

Actors involved: AirTrafficControl Brasila (CINDACTA 1)

Annotation: Flight International

Dec. 05-11, 2006

quoting IFATCA

#### 118 Brazilian military 3-d primary radar provides flight altitude information

Type of Factor: State

Date/Time: Actors involved:

Annotation: Flight International

Dec. 05-11, 2006

quoting IFATCA

#### 119 Military Primary radar altitude information presented to civilian controllers

Type of Factor: State

Date/Time:
Actors involved:

Annotation: Flight International

Dec. 05-11, 2006

quoting IFATCA

#### 120 Military 3-D primary radar altitude information inacurrate

Type of Factor: State

Date/Time: Actors involved:

Annotation: Flight International Dec. 05-11, 2006

quoting IFATCA

## 121 Long-Range triangulation

Type of Factor: Process

Date/Time: Actors involved:

Annotation: Flight International

Dec. 05-11, 2006

quoting IFATCA

#### 122 Controller does not trust primary radar altitude information

Type of Factor: Assumption

Date/Time:

Actors involved: AirTrafficControl Brasila (CINDACTA 1)

Annotation:

#### 123 Legacy enters UZ6

Type of Factor: Event

Date/Time:

Actors involved: Embraer Legacy

Annotation:

#### 124 UZ6 connects Manaus and Brasilia

Type of Factor: State

Date/Time: Actors involved: Annotation:

#### 125 Boeing B737 uses UZ6

Type of Factor: State

Date/Time:

Actors involved: Boeing B737-800

Annotation:

## 126 Legacy flightplan

Type of Factor: State

Date/Time:

Actors involved: Embraer Legacy

Annotation:

#### 127 Planned altitude change from FL370 to FL360 after passing waypoint Brasilia

Type of Factor: State

Date/Time:
Actors involved:

Annotation: Flight International

Dec. 05-11, 2006

#### 128 Planned altitude change from FL360 to FL380 after passing TERES

Type of Factor: State

Date/Time:

Actors involved: Embraer Legacy
Annotation: Flight International

Oct. 17-23, 2005

#### 129 Legacy crew identifies TCAS failure

Type of Factor: Event

Date/Time:

Actors involved: Embraer Legacy

Collision Avoidance System

Annotation: Flight International

May 8-14, 2007

#### 130 TCAS unit displays "TCAS OFF in small white letters on flight display

Type of Factor: State

Date/Time:

Actors involved: Embraer Legacy

Collision Avoidance System

Annotation: Flight International

May 8-14, 2007

#### 131 ATC shift change

Type of Factor: Event

Date/Time:

Actors involved: AirTrafficControl Brasila (CINDACTA 1)

Annotation: Flight International

May 8-14, 2007

#### 132 Controller's electronic flight strip showed Legacy as assigned to FL360

Type of Factor: Event

Date/Time:

Actors involved: AirTrafficControl Brasila (CINDACTA 1)

Embraer Legacy

Annotation: Flight International

May 8-14, 2007

#### 133 Boeing B737 flightplan requested FL370 as cruise altitude

Type of Factor: State

Date/Time:

Actors involved: Boeing B737-800

Annotation: NTSB Safety Recommendation

May 2, 2007

#### 134 No aural warning on TCAS failure

Type of Factor: UnEvent

Date/Time:

Actors involved: Collision Avoidance System

**Embraer Legacy** 

Annotation: NTSB Safety Recommendation

May 2, 2007

#### 135 Boeing B737 does not change altitude

Type of Factor: Event

Date/Time:

Actors involved: Boeing B737-800

Annotation:

#### 136 Legacy maintains FL370

Type of Factor: State

Date/Time:

Actors involved: Embraer Legacy

Annotation:

#### 137 Placing of Legacy crew feet might have disabled Legacy communication devices

Type of Factor: Assumption

Date/Time: Actors involved: Annotation:

## **Actor List**

GOL Flight 1907 Boeing B737-800 Embraer Legacy Embraer Legacy Radar operator Radar operator

ATC Brasilia AirTrafficControl Brasila (CINDACTA 1)

ATC Manaus

TCAS System

Joseph Lepore

AirTrafficControl Manaus

Collision Avoidance System

Pilot of Embrear Legacy 600XL

Sao Jose dos Campos Tower Air Traffic Control at Sao Jose dos Campos Airport, Brazil