

SpanAir Flight 5022 Accident at Madrid on 20 August 2008

Analyst: ***Bernd Sieker***

Report created on: *Fri Nov 07 11:04:02 CET 2008*

Document version: *Document version unknown*



Causalis Limited

Am Petersberg 3

D-33619 Bielefeld

mail: info@causalis.com

web: <http://www.causalis.com>

tel: +49 521 3 29 31 00

fax: +49 521 3 29 31 02

INCIDENT ANALYSIS

Incident description:

On 20 August 2008, SpanAir Flight 5022 ("JK5022") lifted off from Runway 36L, briefly got airborne, rolled left and right, descended back to the grass strip at the right side of the runway, slid and bounced through uneven terrain between runways 36L and 36R, hit obstacles. It finally came to rest, disintegrated and caught fire. Most of the occupants were killed.

1 The Why-Because-Analysis

The reason for performing these analyses is to learn from accidents so that similar occurrences can be avoided in the future.

This cannot stop at a point where for example one human is found to have done something other than the optimal, or even the expected or the prescribed action. Instead, the question must be asked “Why did it make sense to the person at the time, to do what he/she did?” It is known that human beings occasionally make mistakes. Since that does not seem likely to change, it has to be seen that (a) the environment and training are such that as few mistakes as possible are made, and (b) mistakes that have been made can be recognised by the operator and their consequences mitigated or averted.

1.1 Sources

I have prepared this preliminary Why-Because-Analysis of the SpanAir-Accident, based on information from various posters on the well-known Internet forum PPRuNe, and the MD80 Flight Manual. The Official Preliminary report of the CIAIAC only mentions few things beyond a timeline and some known facts, such as that the flaps position was most likely at 0°.

1.2 Assumptions

Most of the nodes in the graph are not known with absolute certainty, however, many of them can be assumed with reasonable confidence. Those which concern actions of the deceased flight crew and some others, which are less certain, have been marked as “ASSUMPTION:”.

1.3 Causes

The Why-Because-Analysis is based on a formal notion of causality, called the counterfactual interpretation: An event or a state A is a necessary causal factor of another event B, if, had A not happened, then B would not have happened either. Arrows in a Why-Because-Graph indicate this causal relationship.

There is a general trend in official investigation reports not to prioritise causes into one Primary Cause and several, ostensibly less important, contributing factors. It is our experience that there is no prioritisation criterion that will distinguish one causal factor over others that can be generally agreed upon. Instead, different involved parties may make their own prioritisation for their specific purposes.

Using only one out of many possible prioritisation criteria and focusing only on the priority cause may divert attention from contributing causes that were also present in many other incidents. This may slow down identifying common causes and delay the implementation of effective and much-needed countermeasures.

Some of the identified causes merit further attention, and I will comment on them below. Please note that this is a preliminary analysis without full knowledge of all the facts. Comments are highly encouraged.

2 Comments

Besides the obvious (if it is going to be confirmed) so-called “pilot error” of not setting the flaps and slats correctly, some other categories of causes can be identified.

I will comment on two of these: training issues and aircraft design issues.

2.1 Training Issues

Others (PJ2 being among the most eloquent in numerous posts on PPRuNe) have given detailed analyses of what aviation safety is about.

I will only highlight two points out of many. The following are not completed analyses and there is no clear-cut conclusion as to what should be done about it. The aim here is only to point towards areas of interest.

- The cause of the RAT probe heater turning on on the ground was apparently not investigated, and the MEL entry allowing dispatch with inoperative RAT probe heating was interpreted to also include a disabled heating, which was otherwise working. Reading and interpreting a Minimum Equipment List in its intended spirit does not

appear to come naturally. It has to be trained. According to the preliminary CIAIAC report, both the technician and the PIC agreed that dispatch was permissible.

- Possibly incomplete and hurried execution of checklists. Even the official report, which goes to great lengths not to talk about any shortcomings of crew actions admits that “some items” of appropriate checklists can be heard on the CVR. Although this may at least in part be due to the poor technical quality of the CVR recordings, it indicates that the reply to the “FLAPS”-challenge was not the prescribed “X degrees, Takeoff”, but perhaps a simple “OK”, likely without looking at either the handle or the indicator.









2.2 Aircraft Design Issues

As can be seen in the WB-Graph, at least the following design decisions were causal to the accident.


- Non-redundancy of ground-air sensing for the Takeoff Warning System (TOWS)
- Absence of a positive indication from the TOWS that the configuration is correct. Both TOWS failure and correct Takeoff configuration are indicated by silence.
- Autoslats stall-recovery system is only operative with slats extended to mid-seal position. It is inoperative with slats retracted.
- Stick-Pusher stall-recovery system is only operative with slats extended. It is inhibited with slats retracted.


Note that I merely wish to raise awareness to the fact that these points are causal factors in this accident. I recognise that introducing changes to existing systems is a large undertaking. I cannot say if and how any of these systems can or should be changed.

Legend of Factorshapes


<i>Factortype</i>	<i>Factorshape</i>
Unspecified Factortype	
Event	
Un-Event	
State	
Process	
Assumption	
Countermeasure	
Contraindication	

Why-Because Graph







Graphtile 0.0




Graphtile 1.0



Graphtile 0.1



Graphtile 1.1



Factor List

- 1 A/C is destroyed
- 2 A/C catches fire
- 3 A/C hits obstacles
- 4 A/C slides and bounces over uneven terrain
- 5 Fuel tanks rupture
- 6 A/C slides off even grass strip at the runway side
- 7 A/C changes its trajectory to the right
- 8 A/C banks heavily, alternating left and right
- 9 Uneven terrain between runways 36L and 36R
- 10 A/C touches the ground at the side of the runway
- 11 A/C reaches high pitch angle
- 12 A/C enters stalled condition
- 13 A/C becomes uncontrollable
- 14 A/C starts to leave ground effect
- 16 A/C airspeed is well below stall speed
- 17 Stall speed is very high
- 18 A/C maintains stalled condition
- 19 A/C starts to descend again
- 20 F/C rotate A/C at calculated speed for FLAPS-11 configuration
- 21 A/C briefly becomes airborne
- 22 Ground effect increases lift close to the ground
- 23 A/C is in "clean" configuration
- 24 ASSUMPTION: F/C do not set correct slat/flap configuration for second takeoff attempt
- 25 "V"-speeds calculated for FLAPS-11 configuration
- 26 ASSUMPTION: F/C believe they have set correct slat/flap configuration
- 27 Recovery procedures (Maximum thrust, FLAPS 15) are initiated too late or not at all
- 28 152 People die
- 29 Uncontained Fuel is ignited
- 30 TOWS aural warning does not sound
- 31 TOWS is inhibited
- 32 TOWS is inhibited in the air
- 33 TOWS gets "in-the-air" signal
- 34 ASSUMPTION: Relay 2-5 is "stuck" in air-mode
- 35 Relay 2-5 controls TOWS
- 36 RAT probe is heated on the ground
- 37 Relay 2-5 controls RAT probe heating
- 38 A/C returns to gate after first taxiing
- 39 Maintenance personnel deactivate RAT probe heating
- 40 Maintenance personnel do not investigate cause for RAT probe heating on the ground
- 41 A/C is dispatched for flight
- 42 Dispatch with inoperative RAT probe heating is allowed when no icing conditions are expected
- 43 No icing conditions expected for the flight
- 44 A/C is late for scheduled flight
- 45 F/C retract slats/flaps while taxiing back to the gate
- 46 A/C starts takeoff run
- 47 A/C taxis to second takeoff attempt
- 48 ASSUMPTION: F/C distracted and/or hurried because of the delay
- 49 F/C do not perform slats/flaps checklist item thoroughly
- 50 Improbably high temperature indication
- 51 F/C notice improbably high temperature indication
- 52 Failure of Relay 2-5 remains undetected
- 53 Relay 2-5 continues to give "in-the-air" signal
- 54 Relay 2-5 controls no other systems with immediately apparent effects on the ground

- 55 Relays 2-5 gives "in-the-air" signal
- 57 No other abnormal symptoms are apparent
- 58 F/C do not perform TOWS check before second takeoff attempt
- 59 F/C are not aware of non-functional TOWS
- 60 SpanAir procedures only call for TOWS check before first flight of day or after prolonged crew absence from aircraft
- 61 A manufacturer recommendation to check the TOWS before every flight was not made mandatory by the authorities
- 62 ASSUMPTION: F/C believe the A/C is configured correctly
- 63 Design and Layout of ground/air sensing and signalling system
- 64 Maintenance personnel are not aware that TOWS function is affected
- 65 F/C are not informed that TOWS is affected
- 66 Auto-slat stall recovery system is inoperative
- 67 Stick-pusher stall recovery system is inoperative
- 68 Auto-slat system depends on slats being extended to "mid-seal" position
- 69 Stick-pusher system depends on slats being extended
- 70 There is no redundancy controlling the air/ground condition of the TOWS
- 71 Handling characteristics of swept-wing T-tail aircraft

Factor List - Details

1 A/C is destroyed

Type of Factor: Event

Date/Time:

Actors involved:

Annotation:

2 A/C catches fire

Type of Factor: Event

Date/Time:

Actors involved:

Annotation:

3 A/C hits obstacles

Type of Factor: Event

Date/Time:

Actors involved:

Annotation:

4 A/C slides and bounces over uneven terrain

Type of Factor: Event

Date/Time:

Actors involved:

Annotation:

5 Fuel tanks rupture

Type of Factor: Event

Date/Time:

Actors involved:

Annotation:

6 A/C slides off even grass strip at the runway side

Type of Factor: Event

Date/Time:

Actors involved:

Annotation:

7 A/C changes its trajectory to the right

Type of Factor: Event

Date/Time:

Actors involved:

Annotation:

8 A/C banks heavily, alternating left and right

Type of Factor: Process

Date/Time:

Actors involved:

Annotation:

9 Uneven terrain between runways 36L and 36R

Type of Factor: State

Date/Time:

Actors involved:

Annotation:

10 A/C touches the ground at the side of the runway

Type of Factor: Event

Date/Time:

Actors involved:

Annotation: Marks in the grass strip from tail cone and main landing gear, possibly also from engine nacelles.

- 11 A/C reaches high pitch angle**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 12 A/C enters stalled condition**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation: Entering stalled condition incurs a significant loss of lift, often asymmetrically.
- 13 A/C becomes uncontrollable**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 14 A/C starts to leave ground effect**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 16 A/C airspeed is well below stall speed**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 17 Stall speed is very high**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 18 A/C maintains stalled condition**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 19 A/C starts to descend again**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 20 F/C rotate A/C at calculated speed for FLAPS-11 configuration**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 21 A/C briefly becomes airborne**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 22 Ground effect increases lift close to the ground**
Type of Factor: State
Date/Time:
Actors involved:
Annotation:

- 23 A/C is in "clean" configuration**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation: More important than the (firmly established) position of the flaps being at 0 degrees, is the position of the slats. The slats decrease the stall speed by some 30 knots, the flaps only by an additional 5-10 knots. Most likely a takeoff with slats deployed, but no flaps would have been uneventful, as V2 (liftoff speed) would have been above slats-only stall speed.
- 24 ASSUMPTION: F/C do not set correct slat/flap configuration for second takeoff attempt**
 Type of Factor: UnEvent
 Date/Time:
 Actors involved:
 Annotation: A complete technical failure involving correct flap handle setting and correct flap/slat indications without actually deployed slats seems extremely remote.
- 25 "V"-speeds calculated for FLAPS-11 configuration**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 26 ASSUMPTION: F/C believe they have set correct slat/flap configuration**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 27 Recovery procedures (Maximum thrust, FLAPS 15) are initiated too late or not at all**
 Type of Factor: UnEvent
 Date/Time:
 Actors involved:
 Annotation: Some Manual revision omit the "FLAPS 15" part.
- 28 152 People die**
 Type of Factor: Event
 Date/Time:
 Actors involved:
 Annotation:
- 29 Uncontained Fuel is ignited**
 Type of Factor: Event
 Date/Time:
 Actors involved:
 Annotation: Possibly by sparks from ground contact, from electrical wiring, or at the hot engine exhaust pipes.
- 30 TOWS aural warning does not sound**
 Type of Factor: UnEvent
 Date/Time:
 Actors involved:
 Annotation: The TOWS has no feedback for "Configuration OK." Absence of any indication can thus either mean "Ok", or a TOWS failure.
- 31 TOWS is inhibited**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 32 TOWS is inhibited in the air**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:

- 33 TOWS gets "in-the-air" signal**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 34 ASSUMPTION: Relay 2-5 is "stuck" in air-mode**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation: R2-5 is the only relay to control TOWS. There is no redundancy.
- 35 Relay 2-5 controls TOWS**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 36 RAT probe is heated on the ground**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 37 Relay 2-5 controls RAT probe heating**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 38 A/C returns to gate after first taxiing**
 Type of Factor: Event
 Date/Time:
 Actors involved:
 Annotation:
- 39 Maintenance personnel deactivate RAT probe heating**
 Type of Factor: Event
 Date/Time:
 Actors involved:
 Annotation: Apparently by pulling the associated circuit breaker, "Z29".
- 40 Maintenance personnel do not investigate cause for RAT probe heating on the ground**
 Type of Factor: UnEvent
 Date/Time:
 Actors involved:
 Annotation:
- 41 A/C is dispatched for flight**
 Type of Factor: Event
 Date/Time:
 Actors involved:
 Annotation: According to the preliminary report, both the captain and the maintenance technician agreed that the aircraft was fit to fly, and dispatch was allowed under MEL.
- 42 Dispatch with inoperative RAT probe heating is allowed when no icing conditions are expected**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation: This may be a misinterpretation of the Minimum Equipment List (MEL). The MEL states that dispatch with inoperative RAT probe heating is allowed. This covers a failed heater, but its applicability to a heater turning on on the ground, and subsequently disabled by pulling a circuit breaker, is dubious.

- 43 No icing conditions expected for the flight**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 44 A/C is late for scheduled flight**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 45 F/C retract slats/flaps while taxiing back to the gate**
 Type of Factor: Event
 Date/Time:
 Actors involved:
 Annotation: Standard procedure when returning to the gate.
- 46 A/C starts takeoff run**
 Type of Factor: Event
 Date/Time:
 Actors involved:
 Annotation:
- 47 A/C taxies to second takeoff attempt**
 Type of Factor: Process
 Date/Time:
 Actors involved:
 Annotation:
- 48 ASSUMPTION: F/C distracted and/or hurried because of the delay**
 Type of Factor: Event
 Date/Time:
 Actors involved:
 Annotation:
- 49 F/C do not perform slats/flaps checklist item thoroughly**
 Type of Factor: Event
 Date/Time:
 Actors involved:
 Annotation: The official preliminary report states that "some items" of the appropriate checklists could be heard on the CVR. Other sources suggest that the "flaps" challenge was made, but the response was only "Ok", instead of the required "11 degrees, Takeoff".
- 50 Improbably high temperature indication**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 51 F/C notice improbably high temperature indication**
 Type of Factor: Event
 Date/Time:
 Actors involved:
 Annotation:
- 52 Failure of Relay 2-5 remains undetected**
 Type of Factor: UnEvent
 Date/Time:
 Actors involved:
 Annotation:

- 53 Relay 2-5 continues to give "in-the-air" signal**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 54 Relay 2-5 controls no other systems with immediately apparent effects on the ground**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation: The two other systems controlled by R2-5 are AC crosstie and radio rack venting.
- 55 Relays 2-5 gives "in-the-air" signal**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 57 No other abnormal symptoms are apparent**
 Type of Factor: UnEvent
 Date/Time:
 Actors involved:
 Annotation:
- 58 F/C do not perform TOWS check before second takeoff attempt**
 Type of Factor: UnEvent
 Date/Time:
 Actors involved:
 Annotation: It is unclear whether or not the crew was absent from the cockpit for a "prolonged" period of time. It is thus uncertain if they should have performed a second TOWS check, according to SpanAir procedure.
- 59 F/C are not aware of non-functional TOWS**
 Type of Factor: UnEvent
 Date/Time:
 Actors involved:
 Annotation:
- 60 SpanAir procedures only call for TOWS check before first flight of day or after prolonged crew absence from aircraft**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation: EASA has released an airworthiness directive mandating that procedures be changed (and the AFM be updated accordingly to include):
- 61 A manufacturer recommendation to check the TOWS before every flight was not made mandatory by the authorities**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 62 ASSUMPTION: F/C believe the A/C is configured correctly**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 63 Design and Layout of ground/air sensing and signalling system**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:

- 64 Maintenance personnel are not aware that TOWS function is affected**
 Type of Factor: UnEvent
 Date/Time:
 Actors involved:
 Annotation:
- 65 F/C are not informed that TOWS is affected**
 Type of Factor: UnEvent
 Date/Time:
 Actors involved:
 Annotation:
- 66 Auto-slat stall recovery system is inoperative**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 67 Stick-pusher stall recovery system is inoperative**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 68 Auto-slat system depends on slats being extended to "mid-seal" position**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation: The auto-slat system extends the slats from "mid-seal" to the fully extended position in case of a stall condition. It does not extend slats from the retracted position.
- 69 Stick-pusher system depends on slats being extended**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation: The stick-pusher system pushes the steering column forwards if a stall condition is detected. It is inhibited if the slats are retracted.

 The independent stick shaker system, and the aural stall warning, are available in all flight phases.
- 70 There is no redundancy controlling the air/ground condition of the TOWS**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation:
- 71 Handling characteristics of swept-wing T-tail aircraft**
 Type of Factor: State
 Date/Time:
 Actors involved:
 Annotation: Swept-wing t-tail aircraft have a natural pitch-up tendency in case of a stall condition. This can be mitigated to some extent by constructional details of the wing controlling flow separation at high angles of attack. However, with increasing AoA, e. g. when the pilot keeps the column pulled back, leading to complete flow separation, the pitch-up tendency returns, exacerbating the stall condition.

 cf. David P. Davies: "Handling the Big Jets", pp. 109ff